DELAWARE STATE HISTORIC PRESERVATION OFFICE

		1			15	THE	GREEN, I	DOVER, DE	19901
		CULTURAL RESC	URCE SUR	VEY			CRS#	K-7360	
						SPO Map	12-13-19		
								South	
							Hundred	Murderkill	
							Quad	Frederica	1.5
							Other		
1.	HIST	ORIC NAME/FUNCTION:	Grodkiewicz	Property/D	welling				
2.	ADD	RESS/LOCATION: 111 B	owers Beach I	Road, Kent	County; No	rth Sid	e of Road		
3.	TOW	N/NEAREST TOWN: _Littl	e Heaven					vicinity?	
4.	MAIN	TYPE OF RESOURCE:	building landscape		structure district		site	Object	
5.	MAII	FUNCTION OF PROPERT	Y: Dwellin	ng					
6.	PROJECT TITLE/ REASON FOR SURVEY (if applicable): SR 1 Little Heaven Interchange								
7.	ADDITI	ONAL FORMS USED:							
	#:	Form:		List prope	erty types:				
	1	CRS 2 Main Building For	n	dwelling	ity types.				
	_ 1	CRS 3 Secondary Buildin	g Form	garage					
	0	CRS 4 Archaeological Sit							
	0	CRS 5 Structure (Building	g-Like) Form						
	0	CRS 6 Structure (Land Fe	ature) Form						
	0	CRS 7 Object Form CRS 8 Landscape Elemen	to Com.						
	1	CRS 9 Map Form	its roilli	N/A					
	0	CRS 14 Potential District	Form	N/A					
8.	SURVE	YOR INFORMATION:							
	Survey	or name:	Lauren C. A	rchibald		8			
	Princip	al Investigator name:	Lauren C. A	rchibald					
	Princip	al Investigator signature:							

Organization:

A.D. Marble & Company Date: July 2004

				,		
10. STATE HISTO plan(s)):	RIC CONT	EXT FRAMEWORK (chec	k all ar	opropriate boxes; refer to st	ate management	
a) Time perio	d(s)	Pre-European Paleo-Indian Archaic Woodland I	Contac	ct		
	>6.	☐ Woodland II				
		1600-1750∀ Contact Per 1630-1730∀ Exploration 1730-1770∀ Intensified a 1770-1830∀ Early Indust 1830-1880∀ Industrializa 1880-1940∀ Urbanization 1940-1960∀ Suburbaniza	and Frand Du trializate ation and B	rontier Settlement rable Occupation tion nd Early Urbanization		
b) Geographi	cal zone	Coastal	eninsu Peninsu	ıla ıla/Cypress Swamp Wilmington)		
c) Historic pe	eriod them	e(s)				
		Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services		Transportation and Common Settlement Patterns and De Architecture, Engineering a Government Religion Education Community Organizations Occupational Organization Major Families, Individuals	emographic Chan and Decorative An	

9. OTHER NOTES OR OBSERVATIONS:

CRS# K-7360

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

<-7360

1.	ADI	DRESS/LOCATION:111 Bowers Beach Road, Kent County;	North Side of Road	
2.	FUN	NCTION(S): historic Residential	current Residential	
3.	YEA	AR BUILT: 1954 CIRCA?: 🛛 ARCHITECT/BUILDER	:	
4.	STY	/LE OR FLOOR PLAN: Bungalow/Cottage		
5.	INT	EGRITY: original site \(\square \) moved \(\square \)		
	<u>if m</u>	noved, from where	other location's CRS #	year
	list a. b.	major alterations and additions with years (if known)		year
6.	CUF	RRENT CONDITION: excellent good	fairpoor	
7.		SCRIPTION: (Describe the resource as completely as possible nks.)	. Use N/A for not applicable; leav	e no
	a.	Overall shape: rectangular Stories: Additions:	1	
	b	Structural system (if known): frame		
	C.	Foundation: materials: concrete block basement: full partial not visible no basem	nent 🗌	
	d.	Exterior walls (original if visible& any subsequent coverings): aluminum	
	e.	Roof: shape: gable materials: asphalt shingles cornice: aluminum dormers: N/A chimney: location(s): exterior concrete block chimney on w	rest wall	
8.	DES	SCRIPTION OF ELEVATIONS:		
	а	n. Facade: Direction: S 1) Bays 2 2) Windows 2 fenestration irregular type 1/1 double-hung trim vinyl shutters vinyl, screw-on		

```
Facade (cont'd)
     Door(s)
                     n/a
                     n/a
        location
        type
                     n/a
        trim
                     n/a
4)
     Porch(es)
Side: Direction: W
                     3
1)
     Bays
2)
     Windows
                     2
        fenestration irregular
                     1/1 double-hung
        type
        trim
                     vinyl
        shutters
                     vinyl, screw-on
3)
     Door(s)
        location
                     near north end
        type
                     simple leaf
                     vinyl
        trim
4)
     Porch(es)
                     has exterior deck
Side: Direction: E
1)
      Bays
                     3
2)
      Windows
                     2
        fenestration irregular
                     paired, 1/1 double-hung
        type
        trim
                     vinyl
        shutters
                     screw-on
3)
      Door(s)
        location
                     near south end
        type
                     simple leaf
                     vinyl
        trim
4)
      Porch(es)
                     n/a
Rear: Direction: N
1)
      Bays
                     1
2)
      Windows
                     1
         fenestration irregular
                     paired 1/1 double-hung
         type
        trim
                     vinyl
         shutters
                     n/a
3)
      Door(s)
                     n/a
         location
                     n/a
         type
                     n/a
```

9. INTERIOR: Not accessible

4)

trim

Porch(es)

n/a

10. LANDSCAPING: Small, grassy lawn to front of house; some low shrubs align the sides of the driveway

exterior deck continues partially to west elevation

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	K-7360	

1.	ADDRESS/LOCATION: 111 Bowers Beach Road, Kent County; North Side of Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN: Rectangular; Vernacular	
5.	INTEGRITY: original site moved original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. b.	<u>year</u>
6. 7.	CURRENT CONDITION: excellent good fair DESCRIPTION:	poor 🗌
	a. Structural system Frame	
	b. Number of stories 1 c. Wall coverings Aluminum	
	d. Foundation n/a e. Roof structural system Gable coverings Asphalt shingles openings n/a	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S1) bays: 22) windows: n/a	
	3) door(s): 2 overhead metal garage doors	
	4) other: n/a	

CRS#	K-7360	
------	--------	--

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: 1, 1/1 double-hung, vinyl
 - 3) door(s): 12 lights over 2 panels
 - 4) other: n/a
- c. Side: direction: N
 - 1) bays: 2
 - 2) windows: 2, 1/1 double hung, vinyl
 - 3) door(s): n/a
 - 4) other: n/a
- d. Rear: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a
- 9. INTERIOR (if accessible):
 - a) Floor plan
- n/a
- b) Partition/walls
- n/a
- c) Finishes
- n/a
- d) Furnishings/machinery
- n/a

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM


CRS#	K-7360	
------	--------	--

1.	ADDRESS/LOCATION:	111 Bo	wers Bea	ch Road, South Murderkill Hundred, Kent County
2.	NOT FOR PUBLICATION		reason:	*
3.	LOCATION MAP:			

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



crs# K-7360

INDICATE NORTH ON PLAN

CRS #K-7360 Grodkiewicz Property

General Description. The Grodkiewicz Property includes a mid-twentieth century, one-story dwelling, a modern garage (c. 1980), and two modern utility sheds. The dwelling occupies a grassy lawn in the midst of a gravel driveway that leads north from Bowers Beach Road and turns west and then south to encircle the dwelling. The garage is located on the north end of the driveway and the utility sheds are located north of the garage. Landscaping includes low shrubs that run along the sides of the driveway and deciduous trees in the lawn. Overall, the property is in good condition.

Main Building. The one-story gable front dwelling is two bays wide and three bays deep and can be characterized as a bungalow form. The frame walls of the dwelling rest on concrete block foundation and are clad in aluminum siding. The roof is clad in asphalt shingles and the eaves are encased in aluminum. In addition to replacement siding and roofing materials, the windows of the dwelling are vinyl replacements flanked by imitation vinyl shutters.

Attached to the north and south elevations of the dwelling are one-story additions. It appears that the addition to the façade (south elevation) was originally an open front porch. The porch is now pierced by two one-over-one double-hung sash windows at the south elevation and a 12-light window over an imitation panel metal door at the east elevation.

There are two paired windows at the east elevation of the main block. Access to the basement level is gained via the storm doors located at the north end of the east elevation.

The north elevation features a singular paired window at the first story of the shed addition and a one-over-one double-hung sash window and a metal vent at the half story of the main block.

The west elevation of the dwelling has a door opening in the one-story addition and two window openings in the main block. A concrete block chimney with a terracotta cap is also attached to the west elevation.

Outbuildings/Garage. A frame garage (ca. 1980), whose walls are clad in aluminum siding and rest on a concrete slab, is located northeast of the dwelling. The side gable garage features two overhead metal garage doors at the south elevation, adjacent to the driveway. The west elevation is pierced by a one-over-one, double-hung sash window and door, while the north elevation features two window openings.

Two frame, one-story utility sheds are located north of the garage. Both feature plywood siding at the walls and asphalt shingles at the gambrel roofs. The northernmost shed is side gambrel in orientation and features a pair of hinged doors at the west elevation flanked by multi-light window openings. The southernmost shed is gambrel front in

orientation, featuring a pair of hinged wooden doors at the west elevation. The sheds are currently used for storage purposes.

Historical Background. The property located at 111 Bowers Beach Road in Little Heaven was formed from the combination of two parcels. On November 6, 1947, Charles W. Baker sold the first parcel to Howard Ney (KCDB F18: 197). On April 20, 1950, Howard Ney sold the property to James E. Flynn for \$225 (KCDB Z18: 385). On July 23, 1951, James Flynn sold the property to Howard Ney for \$400 (KCDB F18: 197). On August 28, 1952, Howard Ney sold the property to Walenty Grodkiewicz and his wife, Felisa Grodkiewicz, for \$300 (KCDB Q19:416). In his will, Walenty Grodkiewicz conveyed both parcels to Felisa Grodkiewicz. On July 8, 1955, Felisa Grodkiewicz sold both parcels to Leon E. Grodkiewicz and his wife, Edith E. Grodkiewicz, for \$7,000 (KCDB A21: 317). Tax assessment records (Kent County Courthouse) state that this house was built in 1954.

Evaluation. The Grodkiewicz Property at 111 Bowers Beach Road is recommended not eligible for listing in the National Register of Historic Places because it does not meet the eligibility criteria established by the National Park Service (NPS 1997). While the Grodkiewicz Property retains a dwelling house representative of mid-twentieth-century residential architecture, the dwelling lacks integrity of materials due to the loss of original windows and addition(s), which obscure several of the original elevations. The loss of integrity affects its ability to convey trends in mid-twentieth-century residential development, so it is recommended not eligible for listing in the National Register under Criterion A.

Property-specific research and documentary research of the area in general did not reveal any associations between the Grodkiewicz Property and significant events or trends in local, state, or national history. Likewise, research did not reveal any associations with significant individuals; therefore, the property is recommended not eligible for listing under Criterion B. The dwelling house does not display the distinctive characteristics of a type, style, or method of construction, nor does it represent the work of a master or possess high artistic value; therefore, it is recommended not eligible under Criterion C in the area of architecture. Archaeological investigations have not yet been conducted on this property; therefore, the resource's eligibility under Criterion D (potential to yield information important to history or prehistory) cannot be assessed at this time.

Bibliography

Kent County Recorder of Deeds (KCDB)

Kent County Deed Books, Kent County Courthouse, Dover, Delaware.

National Park Service (NPS)

1997 National Register Bulletin 15: How to Apply the National Register Criteria for Evaluation. U.S. Government Printing Office, Washington, D.C.